

Elliots of Newbury (UK)

Status	Subject	Detail	Reference information	TNS
<u>Contact:</u> Vintage Glider Club				
<u>Oly 1&2</u>				
	Control cables	damaged in wheel box		02/73
	Rudder	lower hinges cracked		12/76
	Elevator mass balance	insecure		08/90
	Elevator and ailerons	cracks		08/91 & 10/91
	Elevator	cracks in ply "spar web" near to actuator (sketch in TNS)		10/98
	Rudder hinge	lower bearing displaced		04/00
<u>Oly 460 Series</u>				
	Aileron bungees	deteriorated		02/73
	Airbrake lever on root rib	fractured by careless rigging		04/77
	Elevator hinge	castle nut & split-pin insecure		06/94 & 08/80
	Spar fitting washers cracked	inspect & replace as necessary		03/81
M	Main spar failure - corrosion	Mandatory inspection		12/96
M		Mandatory modification	BGA/OLY/460 Series 1/97	08/97
M	Metal Reinforced Spars	Continued airworthiness inspection. Annual and five year check	BGA 025/02/2002 issue 1	02/02