

Glasflugel (Germany)

CONTACT

Glasfaser-Flugzeug-Service GmbH, Hofener Weg 61, D-72582 Grabenstetten Germany Fon +49 (0)7382 1032 Fax +49 (0)7382 1629 e-mail: info@streifly.de

Airworthiness Directives

[LBA](#), [EASA](#), [TC Holder ADs and TNs](#)

Libelle - Std, H201, H201B, H301 & H301B

Libelle in Service Reports (Advisory)

Status	Subject	Detail	Reference Information	TNS
	Wheel axle failures	Inspect for bending & cracking		09/77
	Heavy landing damage	Inspect inter elevator links and brackets		05/81
	Trim springs broken	Inspect for cracks, wear & corrosion		02/88 & 06/84
	Elevator vibration	Minimise backlash		08/85
	Elevator attachment	Cracks in tailplane bracket		12/85
	Wing spar spigots	Mounting plates corroded		04/93
	Elevator travel	Restricted with gear up interference with wheel brake cable		04/97
	Rudder gimbal drive	Cracks reported in 201 Libelle Old type, see AD 2005-118	AD 2005-118	04/04
	Rudder gimbal drive	Possible to incorrectly assemble giving opposite rudder movement		06/05
	Tail plane attachment	Forward attachment bolt broken	TN 201-13	4/2009

Club Libelle (Glasflügel 205)

No in Service Reports (Advisory)

Hornet A, B & C (Glasflügel 206)

No in Service Reports (Advisory)

Hornet C (only)

No in Service Reports (Advisory)

Glasflügel 401 (Kestrel 17) & Glasflügel 604B

No in Service Reports (Advisory)

Mosquito & Glasflügel 304 (304 CZ moved to HpH)

No in Service Reports (Advisory)