

Sportavia (Fournier / Aviostar) (France / Germany)

CONTACT

DGAC Airworthiness Directives

Fournier / Sportavia / Aviostar

RF 3

RF 3 TCDS

Status	Subject	Detail	Reference Information	TNS
M	Wing skin	Inspection for cracks and inspection of glued joints	AD 67-39/1, SB 2	06/83
M	Limitations Main U/C fork failed	Normal category only placard "spinning prohibited" Inspect	AD 75-76	06/83 06/98
M	Restrictions	Airworthiness data sheet	AD64-20	
M	Fuselage	Damage due to excessive humidity	AD1983-015	
M	Controls	L'Hotellier ball & socket with lock plates	AD 1993-001/3	
M	Controls	L'Hotellier ball & socket with locking cams	AD 1994-001/2	

RF 4 and RF 4D

RF 4 SAS

Status	Subject	Detail	Reference Information	TNS
M	Rear fuselage Main U/C fork failed	Bottom & rudder post inspect for water damage Inspect	CAA AD 83-49, SB S-02-82	06/83 06/98
M	Fuselage	Inspection/repair of aft fuselage and vertical fin spar	AD83-15, TN S-02-82	
M	Tailplane	Inspection/replacement of the rear stabiliser mounts	AD85-207, TN S-01-85/1	

RF-5 & 5B

RF 5 TCDS

Status	Subject	Detail	Reference Information	TNS
M	Rear fuselage	Bottom & rudder post inspect for water damage	CAA AD 83-49, SB S-02-82	06/83
M	Elevator mass	Balance to be fitted (RF 5B), Mod 23	CAA AD 79-533/2	06/83
M	Airbrake system bolts in wings Wing fold	Inspect & replace as necessary Unlocked on take off	AD 92-351, SB S-02-91	12/92 02/95 & 12/95
M	Fuselage	Remove ground handling bar from fuselage, inspect for grinding marks in the longitudinal direction of the fuselage centre-line	AD72-24	
M	Propeller	Replacement of propeller boss bolts and centring bushes	AD72-25, WI A04-72 & SL S-02-72	
M	Fin	Inspection/repair of aft fuselage and vertical fin spar	AD83-15, TN S-02-82	
M	Tailplane	Inspection/replacement of the rear stabiliser mounts	AD85-207, TN S-01-85/1	
M	Controls	L'Hotellier ball & socket with lock plates	AD 1993-001/3	
M	Controls	L'Hotellier ball & socket with locking cams	AD 1994-001/2	

Sportavia (Fournier / Aviostar) (France / Germany)