

JSC Sportine Aviacija (Lithuania)

CONTACT

UK Dealership: Ron Bridges, Baltic Sailplanes Ltd. The Gliding Centre, Husbands Bosworth, Lutterworth, LE17

Tel: +44 7540 479204

LAK 12

[LAK 12 TCDS](#)

[LAK 12 Data Sheet](#)

[LAK 12 Flight Manual](#)

| Status | Subject | Detail | Reference Information | TNS |
|--------|------------------------|--|-----------------------|------------------------|
| M | Aft hook installations | Replace with genuine Tost hook | | 04/93 |
| I | Canopy jettison | Care needed to prevent injury by tripping release during maintenance or ground handling After 15 years in service: | | 10/03 |
| M | Service Life | <ul style="list-style-type: none">• Every 5 years/500 hrs in service repeat SB 012.5 Rev 001A,• Every 15 years/1500 hrs in service repeat SB 012.5 Rev 002A• Ultimate service life 3000 hours. SB 012.9 Rev 003A | | 3-2010 |

LAK 12 In Service Reports (Advisory)

| Status | Subject | Detail | Reference Information | TNS |
|--------|----------|-----------------------|-----------------------|------------------------|
| I | Controls | Spliced cable failure | | 1-2009 |

LAK 17A

[LAK 17 TCDS](#)

[LAK 17A Data Sheet](#)

[LAK 17A Flight Manual](#)

| Status | Subject | Detail | Reference Information | TNS |
|--------|---------------------------|---|------------------------------|-----------------------|
| I | Type certificate revision | AUW increased to 500 kg with water (347 kg dry) | Type certificate Nr. 3 | 06/02 |
| I | Type certificate revision | Limitations revised | Type certificate issue 03/03 | 10/03 |
| M | Flight and M Manuals | Revisions | EASA AD 2005-0014 | 04/05 |

LAK 17 In Service Reports (Advisory)

| Status | Subject | Detail | Reference Information | TNS |
|--------|------------------|--------------------------------|-----------------------|------------------------|
| | Engine fuel pump | Mounting bracket found cracked | | 4-2014 |

LAK 19 & 19T

[LAK 19 TCDS](#)

[LAK 19 Flight Manual](#)