

Valentin (Austria/Germany)

CONTACT

Mistral C: Eichelsdorfer GmbH, Hafenstr, 6, D-96052 Bamberg, Germany +49 951 61413

Taifun 17C: KORFF + Co. KG, Unternehmensbereich Luftfahrt, Dieselstrasse 6,D-63128 Dietzenbach, Germany +49 6074 4006 33

Mistral C

[Mistral C TCDS](#)

[Mistral C Data Sheet](#)

[Mistral C Flight Manual](#)

Status	Subject	Detail	Reference Information	TNS
M	Flight controls	Ailerons - residual momentum of ailerons	AD 2001-089, TN329-013	02/01
M	Flight controls	Vertical air brake steering tube cracks	AD 2006-058, TN 329-014	2-2006

Mistral C In Service Reports (Advisory)

Status	Subject	Detail	Reference Information	TNS
	Flight controls - Elevator	Push rod guides loose in fuselage. Also check aileron push rods		2-2011

Taifun 17E

[Taifun 17E TCDS](#)

Status	Subject	Detail	Reference Information	TNS
M	Flight controls	Elevator connection	AD 85-29, TN 3-818	06/86
M	Landing gear	Actuating struts	AD 85-29, TN 3-818	06/86
M	Electrical power	Push button starter	AD 85-29, TN 3-818	06/86
M	Fuel valve	Emergency shut-off	AD 85-29, TN 3-818	06/86
M	Stall characteristics	Improvement	AD 85-129, TN 4-818	06/86
M	Stall warning device	Introduction	AD 85-263, TN 8-818	06/86
M	Tailplane front mounting	Inspect/modify	AD 86-137, TN 10-818	CAA
	Rudder pedals	Inspection		CAA
	Airbrake & wheel brake torque tube	Weld inspection	TN 11-818	02/88
M	Revision of flight manual	Limitations & inspections	AD 87-84, TN 11-818	CAA
M	Revision of empty weight & C of G		AD 87-135, TN 12-818	10/87
M	Airbrake system torsion tube	Deformation- inspect	AD 91-134, SB 24-818	10/91
M	Flap lever - cracks in weld	Replace with modified lever	AD 94-114, SB 28-818	06/94
M	Wings	Safety inspection of main wing attachment	AD2000-392/2, SB 05/818 iss2	10/00 & 02/01
M	Wings	Wing locking mech. Inspection and check	AD 2003-051, SB03/818	02/03
M	Controls	L'Hotellier ball & socket with lock plates	AD 1993-001/3	
M	Controls	L'Hotellier ball & socket with locking cams	AD 1994-001/2	

Valentin (Austria/Germany)

Taifun In Service Reports (Advisory)

Status Subject
Propeller

Detail
Failed propeller due operating in prohibited band

Reference Information

TNS
[4-2014](#)