

Birmingham Guild, Yorkshire Sailplanes, Swales (UK)

Status	Subject	Detail	Reference information	TNS
<u>Contact:</u> Vintage Glider Club				
<u>BG-135, YS55 (Consort), SD3- 15T</u>				
M	Aileron root drive	suspect riveting	SDL/135/Mod 2	
M	Spar at wing root	missing rivets		
M	Aileron push rod	fouls fairlead	SDL/135/2/74	
M	Tailplane final drive	nuts fouling		
M	Release knob failure	no threaded insert		10/74
M	Flying controls bolts too short	stiffnuts not in safely		03/75
M	Tailplane spigots	secure with 'Loctite'		10/75
M	U/C attachments	rivets missing in tube		10/75
M	Air brake mechanism jamming	in fuselage near wing root - inadequate clearance		04/76
	Aileron t/e bonded joint	bond failure		09/77
	Rudder cable stops slippage	Allowing rudder to jam on fin shroud		07/78
	Fuselage to wing lugs worn oval	repair by fitting bushes		10/79
	Spar rear web	cracks near the wing root		12/88
M	Air brake hinge brackets	screws not in safely		08/90