

## Bolkow (Germany)

Status	Subject	Detail	Reference information	TNS
5.4				
5.5	<b><u>Contact:</u></b>			
	LBA Airworthiness Directives			
5.6	<b><u>BÖLKOW (MBB) Phoebus</u></b>			
M	Rudder control arm	cracks aft of seat	AD 75-25	06/75
M	Elevator drive fork end deformed	replace if necessary	AD 76-268, SB 27-60/1	08/76