

Flug Und Fahrzeugwerke (Switzerland)

Status	Subject	Detail	Reference information	TNS
<u>Contact:</u>				
<u>FLUG UND FAHRZEUGWERHE</u>				
<u>Diamant 16.5 & 18</u>				
M	Elevator controls	excess play	AD 16-18	SB 04
M	Elevator controls	alignment at base of fin		09/73
M	Harness attachment	lack of strength - reinforce	SB 105	01/74
M	Wing spar root stubs	reinforce	AD 80-18-09, SB 07 & 08	03/79
	Elevator drive rod fork end	distorted inspect annually & after heavy landings	TN 09	03/79
	Lower rudder hinge failures	annual crack check	AD	12/81
	Rudder pedal rear support failure	inspect annually		02/97