

Wassmer (France)

Status	Subject	Detail	Reference information	TNS
<u>Contact:</u>				
<u>WASSMER</u>				
<u>WA 26P Squale & WA 28F Espadon</u>				
M	L'Hotellier elevator connection	check for correct orientation	AD 78-142(A)	02/98
M	Rear wing attachment	bar cracks check & replace if necessary	AD 79-42(A)	02/98
M	Tailplane supports	annual checks	AD 88-089(A)R1	02/98
M	Rudder cable	annual inspection replace any frayed cables	AD 96-286(A), SB-39	02/97
	WA 28F Drag pin handle insecure	incorrectly assembled		06/99
<u>WA 30 Bijave</u>				
M	Wing to fuselage attachment	fittings cracked - inspect	AD 78-74-(A), SB-02	07/78
M	Canopy catches (front and rear)	insecure - modify		06/93 & 12/90