

Aeromot (Brazil)

CONTACT

X-Imangu UK Ltd, 01904 738653

Department De Aviaco Civil Airworthiness Directives

AMT 100 & 200 X-Imangu

Status	Subject	Detail	Reference Information	TNS
M	Flexible hoses	Replacement	AD 97-04-02, SB-200-79-036	10/98
M	Tailplane front bolt	Inspection	AD 97-07-01, SB 200-53-042	10/97
M	Landing gear fork bolts	Replacement	AD 97-09-06R1, SB 200-32-044	04/98
M	Flight controls	Inspection of elevator driving rod	AD2001-10-01, SB200-27-078	10/01
M	Landing Gear	Inspection of Torque link nut & bolt	AD 2004-11-05	12/04
M	Self Locking Nuts	Replacement if subject to rotational loads	AD 2005-12-01	1-2006
M	Engine Coolant	Rotax engine coolant replacement	AD 2007-01-01, ASB 200-71-106	1-2007