

Centrair (France)

CONTACT

[Societe Nouvelle Centrair](#), Aerodrome, 36300 LE BLANC France.

Tel: +02 54 37 07 96

(It is recommended to communicate in French. Some staff speak a little English)

Airworthiness Directives

DGAC [LBA](#) [EASA](#) [OSAC](#)

Centrair 101 - Pegase

[Centrair 101 SAS](#) [Centrair 101 & 101A Data Sheet](#) [Centrair 101 Flight Manual](#)

Status	Subject	Detail	Reference Information	TNS
M	Rudder	Top rudder hinge cracked	AD 1984-113A, SB 101-4	12/84
M	Tow release guide	Inspection of fittings and cable	AD 1985-002A, SB 101-5	
M	Fuselage	Frame inspection	AD 1985-021A, SB 101-6	04/85
M	Water ballast	Inspection	AD 1986-129A, SB 101-7	10/86
M	Controls Flight	Control supports	AD 1986-128A, SB 101-8	04/85
	Rudder pedals cracked	Inspect "S" cable guides & tubes	SB 101-11	06/91 & 08/96
M	Airbrake operating handle	Colour fades - replace handle	AD 1991-113A, SB 101-12	08/91
M	Wheel brake control	Foul on u/c airbrake handle operated wheel brakes	SB 101-15	10/92
M	Airbrake	Inspection & mod of control	AD 1995-261R3A, SB 101-16R4	
M	Limitations	Reduced max rough air speed (V_{RA}) and max aerotow (V_A)	AD 1993-145R1A, SB 101-17R1	06/94
M	L'Hotellier connections	Annual check (BGA requires locking pins or sleeves)	AD 1997-048A, SB 101-18	12/97
M	Battery	Reinforce mount for front battery, new factory supplied part	AD 1997-149A, SB 101-19 R1	06/97
	A/B & U/C handles	Confusion avoidance fit different shaped handles (minor mod)	MM 101-10	10/98
M	Fixed undercarriages	Inspect for cracks	AD 2003-042A, SB 101-20	12/99
M	Flying controls	Aileron hinge pin inspection	AD2001-247A, SB101-22	06/01
I	Manual revisions	Flight and MM revision status list		06/01
M	Control cables	Cable swaging inspections	AD 2002-274A, SB101-23	10/01
M	Flying controls	Modifications to rudder pedals	AD 2003-095A, SB101-24	12/01
M	Flying Controls	Attachment of Airbrake plastic handle	AD 2004-010A, SB101-25	10/03
M	L'Hotiller couplings	Annual inspections	LBA AD 93-001/3	
R	Seat Harnesses	Inspection of harness attachment	SB 101-30	4-2009
R	Rudder pedals	Inspection/reinforcement or rudder pedal adjustment tube	AD 2010-0099, SB 101-29	3-2010
R	Trim Tab	Trim tab spring life limitation	SB 101-28	2-2011
M	Inspections	Inspections following incidents	AD 2013-0258, SB101-06 r1	5-2013

Centrair (France)

Pegase In Service Reports (Advisory)

Status	Subject	Detail	Reference Information	TNS
	Trim spring failure	Recurring		12/89
	Tailplane attachment (front)	Fitting un-bonded, inspect annually		08/90
	Elevator	Hinge mountings cracks		06/91
	Rudder travel restricted	By unsecured instrument pipes & wires		04/94
	Rudder & hook system jam	Rudder pedal plastic tubes jam on winch hook with rudder adjusted fully forward		10/97
	Air brakes	Apply simulated air loads to check paddle mount bolts for jamming		02/01
	Rudder travel	Restricted by pedal adjustment		10/89
	Elevator	Automatic elevator connector bolt too short and nut not in safety		04/05

Centrair 201 A, B & B1-Marianne

[Marianne 201B Data Sheet](#)

Status	Subject	Detail	Reference Information	TNS
M	Tail plane LE	Inspect for debonding	AD 2002-421A R2, SB 201-06	10/88
	Air brake handle, lower arm	Cracked & failed	SB 201-07	08/90
M	Airbrake operating handles	Colour fades, replace handles	AD 1991-113, SB 201-09	08/91
M	Aileron mass balance	Not secured	AD 1992-088, SB 201-11	06/92
M	Elevator control	Inspection	AD 1995-085A, SB201-13	06/95
M	L'Hotellier connections	Annual check (BGA requires locking pins or sleeves)	AD 1997-048A, SB 201-15	12/97
M	Rear canopy	Modification required to rear jettison Kit 201BE1580	AD 1999-055R1 (A), SB 201-16R1	04/00
M	Service life	Extension of service life	AD 1995-060(A)R1, SB 201-12R2	04/01
M	Flying controls	Aileron hinge pin inspection	AD2001-248A, SB201-19	06/01
I	Manual revisions	Flight and MM revision status list		06/01
M	Control Cables	Cable swaging instructions	AD 2002-272A, SB201-20	10/01
M	Flying controls	Modifications to rudder pedals	AD 2003-096A, SB201-21	12/01
M	Flying Controls	Inspection of tailplane S/N 201.002>201B072	SB201-06 R3	10/02
M	Controls	Inspection and modification to air brake handle	AD F2004-010A, SB201-23 BGA 033/11/2002 iss 1	10/03
M	Controls	Inspection of Airbrake control for cracks	AD F 2004-008A, SB201-24	10/03
M	Fuselage	Damage inspections to tail boom	SB201-25	10/03