

Elliot's of Newbury (UK)

CONTACT

[Vintage Glider Club](#)

Oly 1&2

[Oly 1, 2, 3 Data Sheet](#)

Status	Subject	Detail	Reference Information	TNS
	Control cables	Damaged in wheel box		02/73
	Rudder	Lower hinges cracked		12/76
	Elevator mass balance	Insecure		08/90
	Elevator and ailerons	Cracks		08/91 & 10/91
	Elevator	Cracks in ply "spar web" near to actuator (sketch in TNS)		10/98
	Rudder hinge	Lower bearing displaced		04/00

Oly 460 Series

[Oly 460 Data Sheet](#)

Status	Subject	Detail	Reference Information	TNS
	Aileron bungees	Deteriorated		02/73
	Airbrake lever on root rib	Fractured by careless rigging		04/77
	Elevator hinge	Castle nut & split-pin insecure		06/94 & 08/80
	Spar fitting washers cracked	Inspect & replace as necessary		03/81
M	Main spar failure - corrosion	Mandatory inspection		12/96
M		Mandatory modification	BGA/OLY/460 Series 1/97	08/97
M	Metal Reinforced Spars	Continued airworthiness inspection. Annual and five year check	BGA 025/02/2002 issue 1	02/02