

## Flug Und Fahrzeugwerke (Switzerland)

### CONTACT

FLUG UND FAHRZEUGWERHE

### Diamant 16.5 & 18

Status	Subject	Detail	Reference Information	TNS
M	Elevator controls	Excess play	AD 16-18, SB 04	
M	Elevator controls	Alignment at base of fin		09/73
M	Harness attachment	Lack of strength - reinforce	SB 105	01/74
M	Wing spar root stubs	Reinforce	AD 80-18-09, SB 07 & 08	<a href="#">03/79</a>
	Elevator drive rod fork end	Distorted - inspect annually & after heavy landings	TN 09	<a href="#">03/79</a>
	Lower rudder hinge failures	Annual crack check	AD	<a href="#">12/81</a>
	Rudder pedal - rear support failure	Inspect annually		<a href="#">02/97</a>