Breguet (France)

CONTACT

Airworthiness Directives

EASA

905 Fauvette

Fauvette (Brejeut 905S A, SA)TCDS Fauvette (Breguet 905 S) Data Sheet

Status	Subject	Detail	Reference Information	TNS
M	Tailplane	Rigging pin not secured modify system		10/84
	Centre section	Main spar (alloy) fitting corroded		10/84
	Air brake	Failure of pivots at pilots lever		<u>10/86</u>

BGA Compendium – 01/02