

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 95-085(A)
In case of any difficulty, reference should be made to the French original issue.

CENTRAIR

Models 201 sailplanes

Elevator control

The present Airworthiness Directive concerns models 201 A, 201 B, 201 B1 sailplanes, all serial number.

In order to avoid a possible risk due to an excessive play between the stratified part and the upper metallic part of the push-rod of the elevator control, the following measures are made mandatory at the effective date of this Airworthiness Directive :

- Within the next 3 month and after at each annual inspection and GV proceed to inspection in accordance with CENTRAIR SB Nr 201-13.

Record the application of this Airworthiness Directive on the aircraft logbook.

REF. : SB CENTRAIR Nr 201-13 dated April 12, 1995

EFFECTIVE DATE : MAY 20, 1995