

# Carmam (France)

## CONTACT

For M200 also see under Aer Pegaso

## JP36-15

All known information including the TCDS and ADs is on the EASA website:

<http://easa.europa.eu/document-library/specific-airworthiness-specifications/easasasa005>

Status	Subject	Detail	Reference Information	TNS
M	Lightning strike protection U/C retraction lever	Fit bonding Rubber grip stops lock functioning, secure the grip		BGA <a href="#">12/81</a>
M	No details	Ad 1981-146 sb no 1	Ad 1981-146 sb no 1	
M	No details	Ad 1983-079	Ad 1983-079	
M	No details	Ad 1983-128	Ad 1983-128	

## M-200

Status	Subject	Detail	Reference Information	TNS
	Rudder detached	Lower hinge failed - inspect daily		<a href="#">10/90</a> & <a href="#">10/86</a>
M		Canopy catches insecure		<a href="#">06/93</a>