

Siebert (Germany)

CONTACT

SIE 3

[SIE 3 Data Sheet](#)

Status Subject
M Elevator mass balance mount

Detail
Cracked - reinforce

Reference Information
AD 81/17, TN 264-2

TNS
[03/81](#)