

Wassmer (France)

CONTACT

WA 26P Squale & WA 28F Espadon

[WA 26P Squale Data Sheet](#)

Status	Subject	Detail	Reference Information	TNS
M	L'Hotellier elevator connection	Check for correct orientation	AD 78-142(A)	02/98
M	Rear wing attachment	Bar cracks check & replace if necessary	AD 79-42(A)	02/98
M	Tailplane supports	Annual checks	AD 88-089(A)R1	02/98
M	Rudder cable	Annual inspection- replace any frayed cables	AD 96-286(A), SB-39	02/97
	WA 28F Drag pin handle insecure	Incorrectly assembled		06/99

WA 30 Bijave

Status	Subject	Detail	Reference Information	TNS
M	Wing to fuselage attachment	Fittings cracked - inspect	AD 78-74-(A), SB-02	07/78
M	Canopy catches (front and rear)	Insecure - modify		06/93 & 12/90